Case Study: UK Triton Knoll OWF



- January 2020 present
- 90 turbines, 20 miles off UK coast
- Provided Marine Mammal Mitigation and Noise Measurement services from January 2020
- Mitigation required MMO/PAM Operators, vertically deployed PAM and Acoustic Deterrent Devices
- Noise measurement services required to verify noise predictions and confirm effectiveness of mitigation zone
- Continued operations though COVID-19 offering flexible and committed team





